



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26TE550519
1 Mi In / 1 Mi Out
Stock #: KS26-38

Service Advisor
BECKY DALEIDEN
beckl

A. MISCELLANEOUS	DEALER STATES CABINET DOORS ABOVE THE SOFA HIT EACHOTHER.	Warranty Pay	\$231.00
-------------------------	--	---------------------	-----------------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. The door hinges on cabinets above the sofa, were not adjusted properly.

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$231.00

Labor Cost: \$53.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	1.34	0	0	\$0.00	\$0.00
lafavet	-	0	1.4	1.4	\$231.00	\$53.20

1. Right side cabinet doors above sofa is not hitting each other with adjustment to hinges. Left side cabinet doors above sofa no longer hit each other after adjustments to hinges.

Total Labor Sale
\$231.00

Total Labor Cost
\$53.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B. MISCELLANEOUS	DEALER STATES CABINET DOORS ABOVE SINK HIT EACHOTHER.	Warranty Pay	\$49.50
-------------------------	--	---------------------	----------------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. Hinges on cabinet doors above kitchen sink were not properly adjusted.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$6.90

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	0.21	0.3	0.3	\$49.50	\$6.90
lafavet	-	0	0	0	\$0.00	\$0.00

1. Made the proper adjustments to the cabinet hinges above the kitchen sink, and the doors no longer hit each other.

Total Labor Sale
\$49.50

Total Labor Cost
\$6.90

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C. MISCELLANEOUS	DEALER STATES CABINET DOORS NEXT TO MICROWAVE HIT EACHOTHER.	Warranty Pay	\$16.50
------------------	--	--------------	---------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. Cabinet door hinges, next to microwave, were not properly adjusted.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$2.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	0.09	0.1	0.1	\$16.50	\$2.30
lafavet	-	0	0	0	\$0.00	\$0.00

1. Adjusted the cabinet door hinges properly, and the doors no longer hit each other.

Total Labor Sale
\$16.50

Total Labor Cost
\$2.30

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26TE550519

Service Advisor
BECKY DALEIDEN
beckl

D.	MISCELLANEOUS	DEALER STATES BATHROOM POCKET DOOR REAR ROLLER CAME OFF DOOR.	Warranty Pay	\$66.00
----	---------------	---	--------------	---------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. The bolt for the bathroom pocket door came loose.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$66.00

Labor Cost: \$9.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	0.39	0.4	0.4	\$66.00	\$9.20
lafavet	-	0	0	0	\$0.00	\$0.00

1. Reinstalled bolt for bathroom pocket door. Put pocket door back on the track.

Total Labor Sale
\$66.00

Total Labor Cost
\$9.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

E.	MISCELLANEOUS	DEALER STATES RIGHT & LEFT BLINKERS/BRAKE LIGHTS DO NOT WORK.	Warranty Pay	\$1,659.69
----	---------------	---	--------------	------------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. Improper wire connections from manufacturer. Request 7.5 hr

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$1,650.00

Labor Cost: \$260.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	8.68	8	8	\$1,320.00	\$184.00
lafavet	-	1.01	2	2	\$330.00	\$76.00





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$1,650.00

Labor Cost: \$260.00

1. Found that the wires were swapped inside the junction box on pin box. Test swapped the wires to the correct setup and the brake lights worked as they should. Connected permanently.

Parts

Parts Total Sale Amount \$9.69

Parts Total Cost Amount \$7.45

Name	Quantity	Unit Price	Sale Price	Cost Price
GEOGC28900X - GEOCEL PRO FLEX RV CLEAR 10 OZ	1	\$9.69	\$9.69	\$7.45

Total Labor Sale
\$1,650.00

Total Labor Cost
\$260.00

Total Parts Sale
\$9.69

Total Parts Cost
\$7.45

F. MISCELLANEOUS	DEALER STATES WATER HEATER CONTROL BOARD SCREEN IS CROCKED.	Warranty Pay	\$33.00
-------------------------	--	---------------------	----------------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. Water heater control board screen was in stalled crooked.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	0.15	0.2	0.2	\$33.00	\$4.60
lafavet	-	0	0	0	\$0.00	\$0.00

1. Took the face of the control board off, rotated screen to be level and put the face back on.





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

Total Labor Sale
\$33.00

Total Labor Cost
\$4.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

G. MISCELLANEOUS	DEALER STATES SEWER PIPE OVER MISSING ON BOTH PIPES, RUBBER FEATHERS THERE BUT NO CAPS.	Warranty Pay	\$92.12
------------------	---	--------------	---------

Job added by BECKY DALEIDEN on Tue May 5, 2026 | 1:51 PM

1. Sewer caps missing, cause unknown.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$11.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lindbergj	-	0.41	0.5	0.5	\$82.50	\$11.50
lafavet	-	0	0	0	\$0.00	\$0.00

1. Looked inside and all over the camper for sewer caps. Did not find sewer caps. Ordered 2 new sewer caps. Put new caps on.

Parts

Parts Total Sale Amount \$9.62

Parts Total Cost Amount \$7.40

Name	Quantity	Unit Price	Sale Price	Cost Price
VLPT1020VP - WASTE VALVE CAP, 3IN BAYONET, BLACK, CARDED	2	\$4.81	\$9.62	\$7.40

Total Labor Sale
\$82.50

Total Labor Cost
\$11.50

Total Parts Sale
\$9.62

Total Parts Cost
\$7.40





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

	Category	Sale	Cost
	Labor	\$2,128.50	\$347.70
	Parts	\$19.31	\$14.85
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$2,147.81	\$362.55

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Mon Jun 15, 2026	10:39 AM	11:56 AM	1.28 hrs	W	lindbergj	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Mon Jun 15, 2026	11:56 AM	11:58 AM	0.02 hrs	W	lindbergj	0.3 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Mon Jun 15, 2026	11:58 AM	12:01 PM	0.06 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
B	MISC	Mon Jun 15, 2026	12:33 PM	12:44 PM	0.19 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	Mon Jun 15, 2026	12:44 PM	12:50 PM	0.09 hrs	W	lindbergj	0.1 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Mon Jun 15, 2026	12:50 PM	1:13 PM	0.39 hrs	W	lindbergj	0.4 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Mon Jun 15, 2026	1:14 PM	2:03 PM	0.83 hrs	W	lindbergj	8 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Mon Jun 15, 2026	2:19 PM	3:07 PM	0.81 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
F	MISC	Mon Jun 15, 2026	3:08 PM	3:17 PM	0.15 hrs	W	lindbergj	0.2 hrs
Tag: Regular Hour			Reason: -					
G	MISC	Mon Jun 15, 2026	3:17 PM	3:41 PM	0.41 hrs	W	lindbergj	0.5 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Mon Jun 15, 2026	3:43 PM	3:55 PM	0.21 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Mon Jun 15, 2026	3:58 PM	4:30 PM	0.53 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
E	MISC	Tue Jun 16, 2026	8:07 AM	8:17 AM	0.16 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Jun 16, 2026	1:57 PM	4:26 PM	2.48 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Wed Jun 17, 2026	8:03 AM	8:53 AM	0.84 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Wed Jun 17, 2026	11:00 AM	12:01 PM	1.01 hrs	W	lafavet	2 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Wed Jun 17, 2026	4:13 PM	4:13 PM	0 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Thu Jun 18, 2026	8:06 AM	9:58 AM	1.86 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Thu Jun 18, 2026	10:16 AM	11:08 AM	0.86 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
E	MISC	Thu Jun 18, 2026	11:35 AM	11:41 AM	0.10 hrs	W	lindbergj	-
Tag: Regular Hour			Reason: -					
A	MISC	-	-	-	0 hrs	W	lafavet	1.4 hrs
B	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
C	MISC	-	-	-	0 hrs	W	lafavet	0 hrs





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$2,147.81

RO# : 40598 Tag# : TE550519

Check-in: Tue May 5, 2026 | 1:51 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:38 AM
Promise Time: Sun May 10, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE
ARCADIA 308SLBH
4YDFARP26 TE550519

Service Advisor
BECKY DALEIDEN
beckl

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
D	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
F	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
G	MISC	-	-	-	0 hrs	W	lafavet	0 hrs

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40598	LINK RV	\$2,147.81
57200	40598	LINK RV	-\$2,128.50
67200	40598	LINK RV	\$347.70
14400	lindbergj	LINK RV	-\$218.50
14400	lafavet	LINK RV	-\$129.20
54200	40598	LINK RV	-\$19.31
64000	40598	LINK RV	\$14.85
14000	40598	LINK RV	-\$14.85

