



1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$214.50

RO# : 40640 Tag# : T1HP0165

Check-in: Mon May 11, 2026 | 3:36 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:30 AM
Promise Time: Sat May 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAY
FEATHER
1UJBB0AJ6T1HP0165
1 Mi In / 2 Mi Out
Stock #: 26-24

Service Advisor
BONNIE SEEMANN
bonnie

A.	MISCELLANEOUS	DEALER STATES DOOR LATCH NEED ADJUSTMENT.	Warranty Pay	\$82.50
----	---------------	---	--------------	---------

Job added by BONNIE SEEMANN on Mon May 11, 2026 | 3:36 PM

1. Door latch needs adjusted.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$18.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.35	0.5	0.5	\$82.50	\$18.00

1. Adjusted strike plate on door, and also lubricated handle and latch.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$82.50	\$18.00	\$0.00	\$0.00

B.	MISCELLANEOUS	DEALER STATES SCRATCH ON BATHROOM CABINET OVER SINK.	Warranty Pay	\$49.50
----	---------------	--	--------------	---------

Job added by BONNIE SEEMANN on Mon May 11, 2026 | 3:36 PM

1. Scratch on bathroom cabinet.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$214.50

RO# : 40640 Tag# : T1HP0165

Check-in: Mon May 11, 2026 | 3:36 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:30 AM
Promise Time: Sat May 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAY
FEATHER
1UJBB0AJ6T1HP0165

Service Advisor
BONNIE SEEMANN
bonnie

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$10.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.18	0.3	0.3	\$49.50	\$10.80

1. The scratch in door, looks like something rubbed against the finish of cabinet door, light denting in wood. Would have to verify with warranty if they wanted to repair/replace? There is no repair we can do at this time.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$49.50	\$10.80	\$0.00	\$0.00

C. MISCELLANEOUS DEALER STATES OUTSIDE SHOWER IS NOT HOOKED UP TO COLD WATER. Warranty Pay \$82.50

Job added by BONNIE SEEMANN on Mon May 11, 2026 | 3:36 PM

1. Outside shower had no cold water.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$18.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.45	0.5	0.5	\$82.50	\$18.00

1. Removed outside shower, found cold water line was kinked off at back of shower. removed Pex clamp, removed fitting, cut kinked section of hose out, re-installed fitting in hose, crimped, and connected, tested shower, works as should now. Cleaned and re-sealed shower.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$82.50	\$18.00	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$214.50

RO# : 40640 Tag# : T1HP0165

Check-in: Mon May 11, 2026 | 3:36 PM
 Ready for Pickup: Fri Jun 19, 2026 | 6:30 AM
 Promise Time: Sat May 16, 2026 | 6:00 PM

Customer
 linkautomotive - 2174
 PD7155200709I
 Customer
 1235491
 +1 - (715) 466 - 2222

Billing-Customer
 Same as Customer

Vehicle
 2026 JAYCO JAY
 FEATHER
 1UJBB0AJ6T1HP0165

Service Advisor
 BONNIE SEEMANN
 bonnie

Category	Sale	Cost
Labor	\$214.50	\$46.80
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$214.50	\$46.80

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Jun 17, 2026	3:43 PM	4:04 PM	0.35 hrs	W	turnerl	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Thu Jun 18, 2026	8:02 AM	8:13 AM	0.18 hrs	W	turnerl	0.3 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Thu Jun 18, 2026	8:13 AM	8:40 AM	0.45 hrs	W	turnerl	0.5 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$214.50

RO# : 40640 Tag# : T1HP0165

Check-in: Mon May 11, 2026 | 3:36 PM
Ready for Pickup: Fri Jun 19, 2026 | 6:30 AM
Promise Time: Sat May 16, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAY
FEATHER
1UJBB0AJ6T1HP0165

Service Advisor
BONNIE SEEMANN
bonnie

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40640	LINK RV	\$214.50
57200	40640	LINK RV	-\$214.50
67200	40640	LINK RV	\$46.80
14400	turnerl	LINK RV	-\$46.80

