

Claim Response

Claim: C3032672

Non-Warranty Goodwill Adjustment

Last Modified by:stutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3032672	66663	3/11/2022	3/11/2022	4YDT22022M3106567		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	1/16/2021

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved
Component Model: 6020 Component Serial Number: N 20 32											
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory	21-414 Winn-Tec Complaint: RECALL REGULATOR CUSTOMER STATES THAT HE GOT THE RECALL LETTER FROM THOR..... CHECK AND ADVISE BH DID CONFIRM THAT HE DOES HAVE A KEYSTONE SPRINGDALE AND THE KEYSTONE SPRINGDALE HAS A OPEN RECALL Cause: unit needed a recall Correction: REMOVED RECALLED REGULATOR INSTALLED NEW REGULATOR CHECKED FOR LEAKS (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 71.41
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 146.41

Approved parts & subLet 71.41
Approved labor & subLet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 146.41