

Claim Response

Claim: C3035309

Non-Warranty Goodwill Adjustment

Last Modified by:stutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3035309	66755	3/15/2022	3/16/2022	4YDT28029M3104978		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	10/9/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved

Component Model: 6020

Component Serial Number: N 20 21

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: 21-414 WINN-TEC 6020 PROPANE REGULATOR RECALL Cause: REGULATOR RECALL Correction: REMOVED OLD REGULATOR FROM MAIN HOSE. INSTALLED NEW REGULATOR AND GAS LINES, HOOKED UP TO MAIN LINE. (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 71.41
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 146.41

Approved parts & subLet 71.41
Approved labor & subLet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 146.41