



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73203
Promised Date:
21 APR 26



WO #: 73203

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 24 JUN 26

Invoice#:

Author: BRIAN

Stock Desc: 9652 2026 AVENGER 27REI

Serial#: 5ZT2AVSB2TB941670

Chassis#: 5ZT2AVSB2TB941670

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Date In: 15 APR 26

Time In:

Job #0 - Warranty

CLAIM: 2658904

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: FLOOR DAMAGED

CAUSE: Slide caught loose vinyl

CORRECTION: During inspection of the flooring in the kitchen area, a significant tear and surface damage was identified in the existing vinyl flooring. The damage extended through the wear layer and compromise the integrity of the overall appearance of the floor requiring repair.see picture.

To verify operation and check for any interference, the slide was cycled in and out total of four times. During testing, the slide operated as a design and cleared the affected area each time with no signs of catching or additional damage. In order to complete the proper and seamless repair, replacement of the affected section of vinyl flooring is required. To ensure sufficient material for correct pattern alignment and full coverage during the patch process, an 8 x 15 section of matching vinyl flooring will need to be ordered. This will allow for proper fitment, trimming, and alignment to achieve a professional and durable repair

Removed and replace damaged section of linoleum

Labor

Job #	Description	Total
1	REPAIR FLOOR	0.00

Parts

Part #	Description	Qty	Price	Total
F100699361	LINOLEUM, 96" AVENGER (29303912080)	14.00	12.73	178.22

Sublet

Description	Total
REPAIR FLOOR	570.00

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	150.55	150.55

Subtotal for Job #1: 898.77

Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 73203
Promised Date: 24 APR 26

Parts Total:	178.22
Labour Total:	0.00
Sublet Total:	570.00
Extras Total:	150.55
WORK ORDER TOTAL:	898.77

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 24 Jun 2026

Customer Signature : _____



Customer #: 1000
MYERS "RV" CENTER,
INC.,

