

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13737

|                 |                     |                 |                  |
|-----------------|---------------------|-----------------|------------------|
| Date In:        | 30 JUN 26           | Author:         | DLUCAS           |
| Promised Date:  | 09 JUL 26           | Stock No:       |                  |
| :               |                     | Year:           | 2026             |
| Customer Name:  | 1021 - FOREST RIVER | Manufacturer:   | FOREST RIVER     |
| Address:        | 21815 NETWORK PLACE | Brand:          | PUMA DESTINATION |
| :               | CHICAGO, IL         | Model:          | 403LFT           |
| Postal/Zip:     | 60673-1218          | Miles/Hrs:      |                  |
| Phone#(res):    | 219-534-3167        | Exterior Color: |                  |
| Phone#(bus):    | 219-534-3167        | Unit Type:      |                  |
| Cell Phone:     |                     | License#:       |                  |
| Email:          | NONE                | Tag#:           |                  |
| Purchased Date: |                     | :               |                  |
| Delivery Date:  |                     | :               |                  |
| InService Date: |                     | :               |                  |
| Serial#:        | 1UJBJ02R481JW0132   | :               |                  |

\*\*\*\*\*

| Job # | Description                                                                                                                                                                               | JOB INFORMATION | Type | Bill To    |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|------|------------|
| SC    | CUSTOMER REQUESTS SERVICE CALL TO WILSON LAKE                                                                                                                                             |                 | E    | 308 FISCH  |
|       | CAMPGROUND SITE 45 (NO SIGN) CALL CMR WHEN ON WAY**                                                                                                                                       |                 |      |            |
| 1     | COMPLAINT: CUSTOMER STATES LEAK AT BACK OF TOILET                                                                                                                                         |                 | W    | 1021 FORES |
|       | NEAR FITTING OF TOILET                                                                                                                                                                    |                 |      |            |
|       | CAUSE: pics taken of parts used 1 90 degree 1/2 swivel and a toilet valve                                                                                                                 |                 |      |            |
|       | CORRECTION: cut out leaking fitting behind toilet added in a flair it fitting into water supply line and new toilet valve for toilet re attached to toilet and tested no leaks REQUEST:.5 |                 |      |            |
| 2     | COMPLAINT: CUSTOMER STATES KITCHEN SINK STEADILY                                                                                                                                          |                 | W    | 1021 FORES |
|       | DRIPS WONT SHUT OFF                                                                                                                                                                       |                 |      |            |
|       | CAUSE: pics taken when water is turned of and the faucet is off will not stop steady dripping will need a new complete faucet due to leaking past the seals internally                    |                 |      |            |
|       | CORRECTION: Will need a new complete faucet assembly REQUEST:.6                                                                                                                           |                 |      |            |
| 3     | COMPLAINT: CUSTOMER STATES REAR DOOR IS HARD TO                                                                                                                                           |                 | W    | 1021 FORES |
|       | OPEN AND CLOSE WOULD LIKE LOOKED AT                                                                                                                                                       |                 |      |            |
|       | CAUSE: pics taken adjustments screen door latch                                                                                                                                           |                 |      |            |
|       | CORRECTION: adjustments made to screen door latch the screen is now staying attached to main entry door with out snagging on striker plate REQUEST: .65                                   |                 |      |            |

Continued on page 2

Work Order : 13737

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to      Hrs      Rate      Total
*****
   2  WARR      MANUFACTURER WARRANTY   JS    W-1021      0.48    140.00     67.20
   1  WARR      MANUFACTURER WARRANTY   JS    W-1021      0.50    140.00     70.00
   3  WARR      MANUFACTURER WARRANTY   JS    W-1021      0.50    140.00     70.00
   2  WARR      MANUFACTURER WARRANTY   JS    W-1021      0.02    140.00      2.80
   2  W150      FAUCET, R & R              W-1021      0.00    140.00      0.00

```

```

*****
Job #  Excode   Description   EXTRAS      bill to      Qty      Price      Total
*****
   SC   SC      SERVICE CALL              E-308      0.00      3.75      0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      0.00      210.00      0.00      0.00      0.00      210.00

      Totals      0.00      210.00      0.00      0.00      0.00      210.00

```

&k2S  
&k0S