

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1039630
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAVB0NX025607
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT303RKDSLE
		DEALER RO #	67072
		CLAIM START DATE	05/11/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	RC-003-01-00-004163	22V135, 2022-106 - PATRICK 50AMP SHORE INLETS - INSPECT AND REPLACE - Recall/Electrical/Replace/No Tread Code			
Complaint, Cause, Correction					
Original Note : bhoffman@americanrvcenter.com, 2022-05-11 16:20:56 :: 22V135 THE LUGS ON THE SHORE CORD COULD BE LOOSE CHECK AND ADVISE lug is missing from inlet. need to order replacement for recall. 4/13/22 removed old inlet, replaced with new inlet, sealed inlet with silicone					
	Model #	Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$75.00
Notes					

Submitted	Labor Amt	\$75.00	Approved	Labor Amt	\$75.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$75.00		Total	\$75.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.