

Pre-Authorization

Pre-Authorization number PA03150484 Reference no: 67590

Status: Approved

Approved by WillT

Approved date 6/7/2022

Servicing Dealer	Name	Address	VIN	Retail sold on
------------------	------	---------	-----	----------------

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGGL29N3111209	
------	----------------------	---	--------------------	--

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4120319B	Furnace - Atwood		0.00	3.50	1.50	1	0.60	Complaint:FURNANCE NOT WORKING Cause:FURNACE WOULD NOT KICK ON. FURNACE HAD WIRES NOT CONNECTED AND DEBRIS IN FURNACE...HELPED FIX FURNACE. FOUND THAT THE WIRE IN THE FUSE BOX WAS NEVER TIGHTENED DOWN. THE SCREW WAS ALL THE WAY OUT ON THE TERMINAL. TIGHTENED THE SCREW DOWN AND HOOKED UP THE FURNACE. TESTED AND THE FURNACE NOW WORKS. Correction:HAD TO REMOVE FURNACE TO REMOVE DEBRIS AND TEST. RE ATTACHED WIRE PROPERLY AND ADD A NEW FUSE . AFTER REINSTALLING AND TESTING FURNACE IT KICKED ON AND WORKED KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

Pre-Authorization number PA03150484

1.50For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company