



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27519 SLOAN, DIANE



Estimate: 27519 (Appointment Date: 17 AUG 2026 - Time: 11:00am)

Customer: 51912 - SLOAN, DIANE
Address: 209 EDWARDS ST.
KINGSPORT, TN
37665

Home Phone: 423-426-6960

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 6331

Stock Desc: (6331) 2011 FOREST RIVER

CHEROKEE 27WP

Model: 27WP

Serial #: 4X4TCTC29BY203485

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 15 JUN 11

Date In: 31 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 15 JUN 11

Job #1 - External

CUSTOMER STATES THERE IS A LEAK IN THE FRONT RIGHT CORNER ON CEILING, STATES THERE IS A METAL PIECE THAT HAS COME LOOSE. STATES HE THINKS THE ROOF DECK IS DAMAGED. HAS CONTACTED INSURANCE COMPANY, AND THEY THINK ITS WEAR AND TEAR, BUT STILL WANTS TO GET AN ESTIMATE IN CASE INS DOES NOT COVER.

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

CUSTOMER STATES THERE IS ALSO WATER DAMAGE TO THE WALL INSIDE. HAS CONTACTED INSURANCE COMPANY, AND THEY THINK ITS WEAR AND TEAR, BUT STILL WANTS TO GET AN ESTIMATE IN CASE INS DOES NOT COVER.

Subtotal for Job #2: 0.00

Job #3 - External

CUSTOMER STATES AWNING FABRIC IS TORE, WANTS TO GET ESTIMATE TO REPLACED - PLEASE CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #4 - External

CUST WOULD LIKE TO HAVE COLE LOOK AT IT AND DETERMINE WHAT CASUED THE ISSUES AND THEN CALL THE CUSTOMER

Subtotal for Job #4: 0.00

Job #5 - External

FRONT JACK IS FAULTY CUST HAD TO REMOVE THE CAP AND GEARS



Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 28 Aug 2026

Customer
Estimate

