

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67615
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 50574 - JOHN C. SULAWSKE
Address: 2543 W BOONVILLE-NEW HARMONY RD EVANSVILLE, IN

47720

Phone: 812-568-5200

Stock Number: 11216 - 2022 MONTANA HIGH COUNTRY 385BR 4YDFHMT22NA742910

VIN: 4YDFHMT22NA742910 HIN: SER#: 4YDFHMT22NA742910

Mileage: 0

Work Order Comp: 13 JUN 22

Auth. No:

Dealer #: 1194

Warr. Date: 09 JUN 22

Work Order Date: 04 JUN 22

Inv #: 378353

WO # Job # Description JOB INFORMATION

67615 1 FRONT A/C NOT COOLING
removed inside shroud. hooked up to tester. compressor came on
while hooked up to our tester. removed tester. plugged in wire
harness back into a/c. removed freeze sensor/ thermistor.
replaced freeze sensor with a "tester" and a/c compressor turned
on. need to replace freeze sensor.
REPLACED FREEZE SENOSOR. A/C IS COOLING AS IT SHOULD. INSTALLED
INSIDE SHROUD AND FILTER.

67615 3 WATER LEAK AT THE REAR OF THE CAMPER
water coming out of underbelly. cut open underbelly near outside
shower. located cold water line and found it was leaking.
removed fitting and checked cone washer. cone washer was not
sealing properly. replaced with new cone washer. hot water line
was also loose. tightened both hot and cold lines. turned pump on
to test for leaks. no leaks present. taped underbelly.

67615 4 TRIM PEICE LEADING TO THE BED ROOM IS TOO LONG
trim piece bowed out at ceiling.
cut off a small portion of trim. secured trim with brad nails.

Part No Job# Description PARTS Qty Price Total

188323 1 A/C FREEZE SWITCH 1.00 9.96 9.96
10-7150 3 CONE WASHER SWIVEL SEAL 1.00 0.26 0.26

Claim : 67615

```
*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
```

```
*****
Lab Code     Job#  Description          LABOUR          Hrs       Rate      Total
*****
Z990         1    MISCELLANEOUS REPAIR          0.50     150.00    75.00
Z990         1    MISCELLANEOUS REPAIR          0.50     150.00    75.00
Z990         3    MISCELLANEOUS REPAIR          0.50     150.00    75.00
Z990         4    MISCELLANEOUS REPAIR          0.30     150.00    45.00
*****
```

```
*****
Excode       Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT          1    UPS-FREEZE SWITCH          1.00     11.76     11.76
*****
```

```
Parts Total:      10.22
Labour Total:     270.00
Sublet Total:       0.00
Extras Total:      11.76
```

>>>> Claim Total: 291.98

Customer Signature: _____

Date: _____