

Pre-Authorization

Pre-Authorization number PA03158831 Reference no: 67617 Status: Approved Approved by flins Approved date 6/21/2022
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGN27N3106023 6/5/2022
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4205814A	Speaker - Repair	0.00	2.50	2.50		1	0.30	Complaint:THE FRONT OUTDOOR SPAEKER IS INOP. Cause:wire broken somewhere. Correction:took out speaker and checked wires for ohms no olms took out radio and checked wires good ohms took down ceiling panels and found wire going through roof truss was pinched and would not move cut wire on both sides and hooked together and speaker works put all panels back together and speaker back in and sealed speaker and ceiling staples.
2	1201806B	Power Jack	0.00	0.75	0.50		1	0.50	Complaint:TOUNGE JACK NOT WORKING Cause:FOUND TOUNG JACK NOT WORKING HAS A DEAD SPOT IN IT Correction:REPLACE JACK KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
					3.00				

Pre-Authorization number PA03158831

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company