

aim Response

7/1/2022
10:13:46 am

aim: C3138040

Non-Warranty Goodwill Adjustment

Last Modified by: mbri

Item Reference no.

Repair start date Repair date VIN

Pre-auth

Dealer Repairing dealer name

Labor rate Changed Type warranty rate

Date of Purchase

138040 67756

6/23/2022 6/23/2022 4YDT29028MT433824

1194 Basden's American RV

150.00

0.00 SA21-414 1/21/20

600 E Baseline Rd
Evansville, IN 47725

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

Component Model: 6020

Component Serial Number: N 20 27

Item number	Operation	Description	Svc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory	21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B VIN# MT433824 PART# 380444 Cause: LP REGULATOR RECALL Correction: INSTALLED NW LP REGULATOR AND TESTED (Deking KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & sublet 28.75
Submitted labor & sublet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 103.75

Approved parts & sublet 28.75
Approved labor & sublet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 103.75