

aim Response

7/14/2022
11:51:23 am

aim: C3152108 Non-Warranty Goodwill Adjustment

Last Modified by ambrl

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date Of Purcha
152108	67757	7/6/2022	7/6/2022	4YDT29322M3110106		1194 Basden's American RV 600 E Baseline Rd Evansville, IN 47725		150.00	0.00	SA21-412 5/17/20

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

18749, Dealer claiming 48.79

Component Model: 6020 Component Serial Number: N 19 50

Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: LP RECALL Cause: LP REGULATOR RECAL Correction: INSTALLED NEW LP REGULATOR AND TESTED (Deking KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet	28.75	Approved parts & subLet	28.75
Submitted labor & subLet	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75