

aim Response

7/14/2022
05:04:04 pm

aim: C315200

Non-Warranty Goodwill Adjustment

Last Modified by: tkt

Item Reference no.

Repair start date

Repair date

VIN

Pre-auth

Dealer Repairing dealer name

Labor rate

Changed Type

Date of Purchase

155200 67126

7/13/2022

7/13/2022

4YDT27122LD411166

1194 Basden's American RV

150.00

0.00 SA21-414 9/28/20

600 E Baseline Rd
Evansville, IN 47725

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

Component Model: 6020

Component Serial Number: N 18 34

Operation	Description	Svc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
-----------	-------------	--------------	-----------	------------	-----------	--------	-----	------------	--------

7141442B Safety Advisory 21-414 Winn-Tec

Complaint: KEYSTONE SAFETY ADVISORY LP

REGULATOR RECALL #21-414

SECTION: 71 COMPONENT: 414

OPERATION: 7141442B

PART #380444

Cause: LP REGULATOR RECALL NEEDS

REPLACED

Correction: REPLACED LP REGULATOR AND

TESTED

(Deking KBS)

Submitted parts & sublet	28.75	Approved parts & sublet	28.75
Submitted labor & sublet	75.00	Approved labor & sublet	75.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75