



Warranty Authorization Form

Date: 7/25/2022

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 20944 Unit: 7M5FV453XPA006894
Series: Valor Model: 2023VAL40V13
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 18006 12 VOLT - GENERAL REPAIR

Fault Code: SHORT / OPEN

Serial #:

Model #:

Notes:

Problem: WIRES BUNCHED UP UNDER THE ENTERTAINMENT SLIDE

Time Requested: 2.5

Cause: INSTALL ISSUE

Time Allowed: 2.5

Remedy: had to move wires in slide room because wires underneath were hitting floor and pinching wires possible cutting wires into,took ref out and took cabinet apart to get to wires and drill holes to move wires back,moved wires back and secured,put black silicone around wires to seal,also found coax for tv fell apart and repaired it also,put cabinet back together and installed ref and hooked back up,zip tied spring back up and all is good now.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved