



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 630

CUSTOMER WORK ORDER

WO #: 68140

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: P.HUNT

Location: 0810 CHECK PREAUTH

Stock #: 11239

Stock Desc: 2023 TT KEYSTONE

COUGAR HALF-TON 25RDS

Chassis #: 4YDTCGM27PL500512

Serial #: 4YDTCGM27PL500512

Mileage: 0

Licence:

Invoice #:

Date In: 02 AUG 22

Promised:

Date Sched:

Completed: 10 AUG 22

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI NEW TRAVEL TRAILER

CORRECTION: PREFORMED PDI ON NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: CABINET ABOVE DINETTE IS LOOSE

CAUSE: CABINETTE ABIVE DINNETE IS LOSSE. THE LEFT HINGE WAS LOSE DUE TO A SCREW
THAT AS TO SHORT AND CAME LOSE

CORRECTION: INSTALLED NEW LONGER SCREW

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Subtotal for Job #1: 30.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED



Customer #: 1000
BASDEN'S AMERICAN RV,

W/O: 630

CAUSE: ENTRY DOOR NEEDED ADJUSTED IT WAS HITTING STRIKING PLATE. STRIKING PLATE WAS TO FAR FORWARD CAUSING DOOR TO NOT LATCH RIGHT

CORRECTION: ADJUSTED STRKING PLATE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00
Subtotal for Job #2:			30.00

Job #3 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: SHOWER SURROUND NEEDS SALED UP

CORRECTION: SEALED UP SHOWER SURROUND

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	60.00
Subtotal for Job #3:			60.00

Parts Total: 0.00
Labour Total: 120.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 120.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Aug 2022



Customer #: 1000
BASDENS AMERICAN RV,

