

aim: C3177068

Non-Warranty Goodwill Adjustment

Last Modified by: mbri

Item Reference no.

Repair start date Repair date VIN

Pre-auth

Dealer Repairing dealer name

Labor rate

Changed Type warranty rate

Date of Purchase

177068	68	169	8/4/2022	8/4/2022	4YDT26024K3103500	1194	Basden's American RV	150.00	0.00	SA21-414	2/9/201
--------	----	-----	----------	----------	-------------------	------	----------------------	--------	------	----------	---------

600 E Baseline Rd
Evansville, IN 47725

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
-------------	------	----------	--------------	--------------	--------	------------	--------------	-------------	--------	--------

696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved
--------	---------------------------------	------	------	-------	-------	-------	------	------	------	----------

18749
Component Model: 6020
Component Serial Number: N 18 23

Operation Code	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
----------------	-------------	---------------	-----------	------------	-----------	--------	-----	------------	--------

7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B PART #380444 Cause: LP REGULATOR RECALL Correction: INSTALLED NW LP REGULATOR AND TESTED (Deking/KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved
----------	---	--	------	------	-------	------	---	------	----------

Submitted parts & sublet	28.75	Approved parts & sublet	28.75
Submitted labor & sublet	75.00	Approved labor & sublet	75.00
Submitted freight	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75