

aim Response

8/30/2022
03:43:20 pm

aim: C3197120

Non-Warranty Goodwill Adjustment

Last Modified by: ambri

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
------	---------------	-------------------	-------------	-----	----------	--------	-----------------------	------------	-----------------------	------	------------------

197120	68385	8/25/2022	8/25/2022	4YDT27423L3102677		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	10/26/2
--------	-------	-----------	-----------	-------------------	--	------	---	--------	------	----------	---------

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
-------------	------	----------	--------------	--------------	--------	------------	--------------	-------------	--------	--------

		1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved
--	--	------	------	------	-------	------	------	------	------	----------

Item code not part of recall
Component Model: 6020
Component Serial Number: N 17 49

Item number	Operation	Description	Srvc advisory	Sub hours	Apv'd Hours	Labor amt	Sublet	Qty	Base Hours	Status
-------------	-----------	-------------	---------------	-----------	-------------	-----------	--------	-----	------------	--------

7141442K		Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: LP REGULATOR RECALL. UNIT HAS ON IT A N -17 -49 WHICH DOS NOT NEED TO BE REPLACED Correction: NO ACTION REQUIRED		0.30	0.30	45.00	0.00	1	0.30	Approved
----------	--	--	--	------	------	-------	------	---	------	----------

Submitted parts & sublet 0.00
Submitted labor & sublet 45.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 45.00

Approved parts & sublet 0.00
Approved labor & sublet 45.00
Approved freight: 0.00
Tax: 0.00
Total approved: 45.00