

aim Response

8/30/2022
05:07:13 pm

aim: C3198231 Non-Warranty Goodwill Adjustment

Last Modified by ambri

aim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type warranty rate	Date Of Purchase
198231	68388	8/26/2022	8/26/2022	4YDT17510MK410843		1194 600 E Baseline Rd Evansville, IN 47725	Basden's American RV	150.00	0.00	SA21-414 8/8/202

ny Item de number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

18749. Dealer claiming 48.79/56.11

Component Model: 6020 Component Serial Number: N 19 44

ny Operation de	Description	Srv advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
-----------------	-------------	--------------	-----------	------------	-----------	--------	-----	------------	--------

7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444		0.50	0.50	75.00	0.00	1	0.50	Approved
----------	--	--	------	------	-------	------	---	------	----------

Cause: LP REGULATOR RECALL
Correction: INSTALLED NEW LP REGULATOR
AND TESTED

(Deking/KRV)

Submitted parts & subLet	28.75	Approved parts & subLet	28.75
Submitted labor & subLet	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75