

aim: C3203014 Non-Warranty Goodwill Adjustment Last Modified by ambrl

aim Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date Of Purchase
203014 68429	8/31/2022	8/31/2022	4YDT25722K3151643		1194 Basden's American RV 600 E Baseline Rd Evansville, IN 47725		150.00	0.00 SA21-414	7/5/201

Item #	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
692585	Regulator - Kit - Auto Change	0.00	0.00	48.79	15.00	0.00	0.00	0.00	0.00	Denied
ts claimed not supported by repair detail										
Component Model: 6020 Component Serial Number: N 18 12										
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved
Component Model: 6020 Component Serial Number: N 18 12										

Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: LP REGULATOR RECALL Correction: REPLACED REGULATOR AND TETSTED		0.50	0.50	75.00	0.00	1	0.50	Approved

(Deking/KRV)

Submitted parts & subLet	28.75	Approved parts & subLet	28.75
Submitted labor & subLet	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75