

Claim Response

Claim: C3210750

Non-Warranty Goodwill Adjustment

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3210750	68522	9/12/2022	9/12/2022	4YDT3112XL3101458		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	7/18/2019

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

5218749

Component Model: 6020

Component Serial Number: N 18 26

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: REGULATOR RECALL Correction: INSTALLED NEW REGULATOR AND TESTED (Deking/KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet	28.75	Approved parts & subLet	28.75
Submitted labor & subLet	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	<u>103.75</u>	Total approved:	<u>103.75</u>