

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS Authorized	
BASDEN RV CENTER INC		CLAIM 1278228	
DBA AMERICAN RV CENTER		CLAIM ORIGIN WEB	
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN 5ZT2CAVB1NX026135	
USA		CHASSIS VIN	
Labor rate: \$150.00		MILEAGE 0	
OWNER INFORMATION		SITE/WAREHOUSE 205 / 205	
JOEL PATTEN		ITEM # ACAT303QBCKLE	
4233 TRINITY DR		DEALER RO # 68737	
Newburgh, IN 47630		CLAIM START DATE 10/14/2022	
USA		CLAIM END DATE 01/01/1900	
Retail Date of Purchase 05/14/2022		WARRANTY EXPIRATION DATE 05/14/2023	

Claim Line Details

Labor					
Line# 1	Operation Code 30-102-12-00-002691	Operational Description Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-14 11:24:48 :: FIX WALLPAPER IN THE BEDROOM THAT IS COMING LOOSE CUT WALL PAPER AND PEEL BACK, THEN SPRAYED ANHESVIE. SHOT MORE STAPLES IN WALL TO HOLD PANEL IN PLACE. TRIMED OUT WITH COLOR MATCHING TRIM TAPE.				
	Model #	Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$75.00
	Notes pending vender review. PLEASE LET ME KNOW THE UPDATE 10-14-22 Excessive amount of time, adjusted to time to do job repair				
Labor					
Line# 2	Operation Code 20-66-01-17-000668	Operational Description Entry Door Lock - Exterior/Entry Doors/Replace/Latch			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-14 11:26:22 :: LOCK ON THE HANDLE (NOT DEADBOLT) IS NOT LOCKING THE DOOR, HE CAN STILL PULL IT OPEN replaced with new door handle lock. checked and aligned til door shut proper. NEW KEYS STAPLE TO WO PAPER				
	Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$60.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00
	Notes Excessive amount of time requested. Adjusted to flat rate				
Labor					
Line# 3	Operation Code RC-003-22-00-004205	Operational Description 22V477, 2022-358 - BREAKAWAY SWITCH WIRING - INSPECT AND REWIRE - Recall/Electrical/Rewire/No Tread Code			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-14 11:27:02 :: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL cut underbelly to gain access to the wires. took pictures of problem. fixed wires to recall standards				
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00
	Notes				

Submitted	Labor Amt	\$255.00	Approved	Labor Amt	\$165.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$255.00		Total	\$165.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.