

3-Authorization number PA03271022 Reference no: 68746 Status: Approved Approved by steic Approved date 10/6/2022
Billing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTS6N27P3101004
600 E Baseline Rd
Evansville, IN 47725

Item	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	420390	GB Detector, CO - Re	0.00	0.30	0.20		1	0.20	Complaint: CARBON DETECTOR NOT WORKING Cause: INTERNAL FAILER OF THE DETECTOR Correction: NEED TO REPLACE
KRV - VCB									

3-Authorization number PA03271022
0.20

paper claims only use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the