

aim Response

11/22/2022
01:51:49 pm

aim: C3272714

Last Modified byambri

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type warranty rate	Date Of Purcha
------	---------------	-------------------	-------------	-----	----------	--------	-----------------------	------------	----------------------------	----------------

272714	69341	11/17/2022; 11/17/2022	4YDTSGG19NW10916	1194	Basden's American RV	150.00	0.00	WARR	5/11/20
600 E Baseline Rd Evansville, IN 47725									

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
		1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

Component Model: V-330710 3/16/2016 Component Serial Number: RPO-0007935632

Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7143442K	Safety Advisory 22-434 Lippert A (INSPECTION) Complaint: #22-434 LIPPERT AWNING RECALL Cause: RECALL Correction: TOOK PICS AND CHECKED ENDS OF AWNING AND IT IS GOOD.		0.30	0.30	45.00	0.00	1	0.30	Approved

Submitted parts & sublet	0.00	Approved parts & sublet	0.00
Submitted labor & sublet	45.00	Approved labor & sublet	45.00
Submitted freight	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	45.00	Total approved:	45.00