

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 69398
 MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV
 Customer: 53258 - BRANDON LANCASTER
 Address: 11420 MERLIN PL EVANSVILLE, IN

47725

Phone: 812-629-7812

Stock Number: 11196 - 2022 RETRO 171DRD 59CCC4519NL005120

VIN: 59CCC4519NL005120 HIN: SER#: 59CCC4519NL005120

Mileage: 0 Work Order Comp: 30 NOV 22

Auth. No: Dealer #:

Warr. Date: 26 NOV 22 Work Order Date: 21 NOV 22 Inv #: 385966

 WO # Job # Description JOB INFORMATION

69398 2 TV HAS NO CHANNELS
 TV HAS NO CHANNELS.
 Test TV will not pickup channels either inside shop or outside.
 Removed booster from wall to check coax connections. Removed
 antenna plate in bedroom. Bedroom coax has an orange cable. It
 is connected to the cable port on booster. Outside cable port is
 connected to the antenna on back of booster. Coax from antenna
 is connected to the set 2 on booster. Changed all coax cables to
 correct connectors on back of booster. Ran a channel search
 inside shop. TV found 4 channels. Remounted all antenna plates.

69398 3 THE TRAILER BRAKES ARE NOT WORKING.
 I HAD TO ADJUST THE BRAKES ON THE TRAILER. THE BRAKES WERE SO
 LOOSE THAT THE BRAKE AWAY SWITCH WOULD NOT STOP THE WHEEL FROM
 SPINNING. AFTER ADJUSTING THE BRAKES, I TEST PULLED THE TRAILER
 AND TESTED THE BRAKES.

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	2	MISC LABOUR CODE (EXTERNAL)	1.00	150.00	150.00
Z990	3	MISC LABOUR CODE (EXTERNAL)	0.50	150.00	75.00

Parts Total: 0.00
 Labour Total: 225.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 225.00