

e-Authorization

1/23/20
09:29:19

3-Authorization number PA03347955 Reference no: 69678 Status: Approved Approved by jhnhj Approved date 1/16/2023
Billing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV
600 E Baseline Rd
Evansville, IN 47725 4YDTSG12XN3102213 1/28/2022

Item	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2300906B	Entrance Door - h	0.00	0.20	0.20		1	0.30	Complaint: REAR MAIN ENTRY DOOR HAS SEAL THAT IS COMING LOOSE AND WILL NOT STAY Cause: PLASTIC TRIM INSERT IS WARPED IN BOTH SIDES AND IS NOT SITTING FLUSH. NEED TO REPLACE BOTH SIDES. Correction: WILL HAVE TO R&R TRIM
2	3303806B	Sofa - Jack Knife	0.00	1.00			1	0.50	Complaint: COUCH HAS A SAG IN THE MIDDLE. SEE WHAT NEEDS TO BE DONE TO FIX Cause: COUCH FRAME IS BENT IN THE MIDDLE. COUCH MORE THANK LIKELY NEEDS REPLACED TO CORRECT THIS. Correction: NEED TO REPLACE THE COUCH IT HAS FAILED
3-Authorization number PA03347955					0.20	KRV - The issue submitted is not considered a warranty defect in materials or workmanship.			

paper claims ~~only~~ use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the