

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69928
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10760 - 2023 FREEDOM EXPRESS 259FKDS 5ZT2FERB3PW026302
VIN: 5ZT2FERB3PW026302 HIN: SER#: 5ZT2FERB3PW026302
Mileage: 0 Work Order Comp: 09 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 24 FEB 23 Inv #: 388327

WO # Job # Description JOB INFORMATION

69928 1 DINNETTE CABINET WONT REACH
DINEETTE CABNIET WONT REACH AS HINGES WERE LOSSE AND LATCHES NOT
IN PROPER SPOTS. REMOVED SCREWS AND ATTACHED LONGER SCREWS INSTEA
OF THE SHORT ONES THAT WERE ORGIANLLY ATTACHED. THEN MOVED UPO
LATCH SO THAT IT WOULD LATCH PROPERLY AND THEN TESTED DOOR.
DINEETTE CABNIET WONT REACH AS HINGES WERE LOSSE AND LATCHES NOT
IN PROPER SPOTS. REMOVED SCREWS AND ATTACHED LONGER SCREWS INSTEA
OF THE SHORT ONES THAT WERE ORGIANLLY ATTACHED. THEN MOVED UPO
LATCH SO THAT IT WOULD LATCH PROPERLY AND THEN TESTED DOOR.

69928 2 KITCHEN CLOSET DOOR RUBS
KITCHEN CLOSET DOOR WAS RUBING DUE TO STRIKE PLATE BEING TO FAR
OUT. REMOVED SCREWS AND READJUSTED STRIKE PLATE
KITCHEN CLOSET DOOR WAS RUBING DUE TO STRIKE PLATE BEING TO FAR
OUT. REMOVED SCREWS AND READJUSTED STRIKE PLATE

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00

Parts Total: 0.00
Labour Total: 64.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 64.00

Customer Signature: _____

Date: _____