

Pre-Authorization

Pre-Authorization number PA03385158 Reference no: 69936 Status: Approved Approved by papca Approved date 3/8/2023
Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTCGP21NV507131
600 E Baseline Rd
Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3304502F	Shade - Pleated -	0.00	0.20	0.10		1	0.10	Complaint:BLIND IN SLIDE OUT WONT STAY DOWN Cause:adjusted tension on blind knob. Correction:adjusted tension on blind knob. KRV – REPAIR ONLY approved.
2	5102419A	Light, 12V Interior	0.00	0.20	0.20		1	0.20	Complaint:1 LIGHT IN CEILING DOES NOT WORK Cause:took light down and wire was not crimped all the way, recrimped, light works. Correction:took light down and wire was not crimped all the way, recrimped, light works. KRV – REPAIR ONLY approved.
3	4107416B	A/C - Dometic - Fi	0.00	0.40	0.40		1	1.50	Complaint:REAR A/C MAKING NOISE ON ROOF Cause:took cover off of rear a/c and found fan blade was hitting shroud,found excess plastic from mold,cut excess off,put back together and it is not hitting anymore. Correction:took cover off of rear a/c and found fan blade was hitting shroud,found excess plastic from mold,cut excess off,put back together and it is not hitting anymore. KRV – REPAIR ONLY approved.
					0.70				

Pre-Authorization number PA03385158

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company