

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70052
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11192 - 2023 CATALINA SUMMIT SERIES 261BH 5ZT2CARB5PU041736
VIN: 5ZT2CARB5PU041736 HIN: SER#: 5ZT2CARB5PU041736
Mileage: 0 Work Order Comp: 17 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 08 MAR 23 Inv #: 388612

WO # Job # Description JOB INFORMATION

70052 4 THE REMOTE FOR THE RADIO IS MISSING - JBL AURA-CUBE
no remote
get m# and ser#, turn in PO

70052 1 BATHROOM DOOR WONT LATCH
walls not lineing up
wall for bathroom door 3/4 in out of position with bottom of
door sticking out of door frame by 3/4 in at bottom and flush at
top, remove door, trims and door jam, remove wall board get to
mounting screws for wall and move as far as it has bath sink
cabnet on one side and refer cabnet on other side, pull staples
from trim to reuse we do not have new trim strips to match wall
board, install wall board, trim strips, door jam, door and reset
catch for door latch, door wil latch now, clean up,

70052 2 FRONT COMPARTMENT LINOLEUM HAS A TEAR IN IT TOWARDS THE MIDDLE
noted on delivery
pull up vinal and work glue under vinal floor ing and press down

70052 5 THE TELIVISION IS NOT RECIEVING SIGNAL AT ALL.
BOOSTER IS MISS WIRED
TRACE WIRES FOUND CABLE IN WIRE CONETED TO ANTENA IN ON BOOSTER,
ANTENA IN WIRE ON TV #2 OUT ON BOOSTER, TV #2 WIRE ON CABLE IN ON
BOOSTER, REWIRE BOOSTER AND TEST FOR TV

70052 6 WHEN TURNING THE WATER PUMP ON THE PUMP MAKES A LOT OF NOISE

Claim : 70052

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
          water lines from pump rubbing cabnet and drain lines
          remove accesse panels in cabnet, found water lines from pump
          rubbing cabnet and drain lines, use window foam sel to put beteen
          lines and cabnets, and drain lines and test, put cabnet back to
          gether

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
F100353660      4      REMOTE, STEREO TO JBL-AURA-CUBE 2      1.00      18.98      18.98

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.00      160.00      0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.00      160.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)      1.25      160.00      200.00
Z990      1      MISC LABOUR CODE (EXTERNAL)      1.25      160.00      200.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      0.50      160.00      80.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.80      160.00      128.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.50      160.00      80.00

```

```

*****
Excode      Job#      Description      EXTRAS      Qty      Price      Total
*****
FRT      4      UPS-REMOTE      1.00      15.84      15.84

```

```

Parts Total:      18.98
Labour Total:      688.00
Sublet Total:      0.00
Extras Total:      15.84

```

```

>>>>> Claim Total:      722.82

```

Customer Signature: _____

Date: _____