



Warranty Authorization Form

Date: 4/18/2023

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 36552 Unit: 7M5FA362XNC300518
Series: Avenue Model: 2022AVE32RLS
Notes:
Status: Approved

Dealer Information

American RV (812) 867-5200	Basden RV Center, Inc. DBA/ American RV 600 E Baseline Rd, Evansville, IN 47725	Requestor: Ben Hoffman Return Fax #: Email: bhoffman@americanrvcenter.com
-------------------------------	---	---

Operation Line 1

Flat Rate Code: 16003B AIR CONDITIONER - FREEZE SWITCH -
REPLACE - COLEMAN (Photos required)

Fault Code: PART MISSING

Serial #: 220175307

Model #: 98203-0650

Notes: COLEMAN MACH MODEL 98203-0650 SERIAL
NUMBER 220175307

Problem: LIVING ROOM A/C NOT COOLING

Cause: FOUND FREEZE SWITCH MISSING

Remedy: RAN AC AND FOUND WAS DRAWING 2 AMPS I PULLED V PLENIUM DOWN AND
NOTICED THE BOARD HANGING DOWN AND THERE WAS NO FREEZE SWITCH JUST
CONNECTORS SO I INSTALLED FREEZE SWITCH AND THE COMPRESSOR CAME ON AND
HAD 38 DEGREES COMING OUT THE VENTS.

Part Return Req: No

Status: Approved

Time Requested: 1

Time Allowed: 1

Sublet Repairs: 0.00