



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70409

CUSTOMER WORK ORDER

WO #: 70409

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0510 CHECK PARTS

Stock #: 11267
Stock Desc: 2023 TT KEYSTONE
COUGAR HALF-TON 30BHS
Chassis #: 4YDTCGP23PV505464
Serial #: 4YDTCGP23PV505464
Mileage: 0
Licence:

Invoice #:
Date In: 18 APR 23
Promised:
Date Sched:
Completed: 30 APR 23
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: KITCHEN DRAWER WONT LATCH

CAUSE: KITCHEN DRAWER WOULDNT LATCH AS IT WAS OFF THE TRACK. TOOK DRAWER OUT AND INSTALLED PROPERLEY

CORRECTION: KITCHEN DRAWER WOULDNT LATCH AS IT WAS OFF THE TRACK. TOOK DRAWER OUT AND INSTALLED PROPERLEY

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: MINI FRIDGE HAS A DENT IN IT

CAUSE: MINI FRIDGW IN OUTSIDE REAR COMPARTMENT HAS A DENT IN IT WHERE THEY DIDNT MOUNT THE FRIDGE IT WAS LOSSE AND CASUING DAMAGE

CORRECTION: MINI FRIDGW IN OUTSIDE REAR COMPARTMENT HAS A DENT IN IT WHERE THEY DIDNT MOUNT THE FRIDGE IT WAS LOSSE AND CASUING DAMAGE. NEED NEW ONE



Customer #: 1000
BASDEN'S AMERICAN RV,

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	76.80
Z990	MISCELLANEOUS REPAIR	RAB	3.20

Parts

Part #	Description	Qty	Price	Total
616961	Refrigerator - 1.7 Cu Ft - RH - Hot Point - Energy Star - Black	1.00	160.60	160.60

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-REFER	1.00	36.22	36.22

Subtotal for Job #2: 276.82

Job #3 - Warranty

COMPLAINT: MICROWAVE SPINDLE PART MISSING

CAUSE: MICROWAVE MISSING SPINDLE CAUSING IT NOT TO ROTATE NEEDS NEW ONE

CORRECTION: MICROWAVE MISSING SPINDLE CAUSING IT NOT TO ROTATE NEEDS NEW ONE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	RAB	0.00
Z990	MISCELLANEOUS REPAIR	DWW	48.00

Parts

Part #	Description	Qty	Price	Total
4938	Microwave - .9 Cu Ft - NoTrim Kit - Black - FMSN09-BL	1.00	193.15	193.15

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-MICROWAVE	1.00	28.18	28.18

Subtotal for Job #3: 269.33

Job #4 - Warranty

COMPLAINT: BATHROOM CABINET NEEDS ADJUSTED

CAUSE: BATHROOM CABINET DOOR NEEDED ADJUSTED WASNT HITTING LATCH. ADJUSTED DOOR HINGES AND LATCH SO IT WOULD ALIGN UP AND SHUT PROPERLEY

CORRECTION: BATHROOM CABINET DOOR NEEDED ADJUSTED WASNT HITTING LATCH. ADJUSTED DOOR HINGES AND LATCH SO IT WOULD ALIGN UP AND SHUT PROPERLEY

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	16.00

Subtotal for Job #4: 16.00

Parts Total: 353.75
 Labour Total: 176.00
 Sublet Total: 0.00
 Extras Total: 64.40
WORK ORDER TOTAL: 594.15

Customer #: 1000
 BASDEN'S AMERICAN RV,

