

# e-Authorization

5/11/20  
11:38:45

e-Authorization number PA03434108 Reference no: 70560 Status: Approved Approved by steic  
 VIN Retail sold on Approved date 5/11/2023

34 Basden's American RV Basden's American RV 4YDTSGN27P3101004 5/5/2023  
 600 E Baseline Rd  
 Evansville, IN 47725

Job #	Root Job Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5101906B Light, Clearance	0.00	0.40	0.40		1	0.20	Complaint: BOTH TOP REAR MARKER LIGHTS DO NOT WORK Cause: TOOK LIGHTS OFF AND CUT WIRES TESTED ON BATTERY TO MAKE SURE THEY WERE BAD AND THEY WERE, GOT 2 NEW LIGHTS AND HOOKED UP WIRE AND INSTALLED, TESTED AND THEY ARE GOOD, SEALED LIGHTS, ALL GOOD. Correction: TOOK LIGHTS OFF AND CUT WIRES TESTED ON BATTERY TO MAKE SURE THEY WERE BAD AND THEY WERE, GOT 2 NEW LIGHTS AND HOOKED UP WIRE AND INSTALLED, TESTED AND THEY ARE GOOD, SEALED LIGHTS, ALL GOOD. KRV - VCB
				0.40				

e-Authorization number PA03434108

Paper claims only use one pre-authorization number per warranty claim for  
 multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the