

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71367
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 40167 - STEVEN W. MCCORKLE
Address: 1704 MICHAEL AVE.
MT. CARMEL, IL
62863
Phone: 618-262-3717
Stock Number: 11195 - 2022 PARADIGM 295MK 7M5FP3421NB201643
VIN: 7M5FP3421NB201643 HIN: SER#: 7M5FP3421NB201643
Mileage: 0 Work Order Comp: 25 AUG 23
Auth. No: Dealer #:
Warr. Date: 24 MAY 23 Work Order Date: 07 AUG 23 Inv #: 395602

WO # Job # Description JOB INFORMATION

71367 5 CUSTOMER WAS UNABLE TO GET THE INVERTER TO POWER UP AT HIS HOME.
CUSTOMER THEN TRAVELED TO HIS DESTINATION AND THE INVERTER
POWERED UP. CUSTOMER IS CONCERNED THAT THERE MAY BE A LOOSE
CONNECTION.
Push button from inside or out and it will not turn on.
INSTALLED NEW INVERTER AND TESTED OPERATION.

71367 1 BEDROOM AC WILL NOT RUN ON LOW FAN. FAN WILL RUN ON ALL OTHER
SETTINGS AND THE COMPRESSOR RUNS.
.
Found low speed wire for fan disconnected. Pulled plenum down.
And reconnected wire and tested operation.

71367 2 CHECK THAT ANTENNA IS HOOKED UP FOR THE RADIO, CUSTOMER STATES HE
DOES NOT GET ANY STATIONS.
.
Found antenna wire disconnected. I reconnected and tested
and had several channels.

71367 3 WATER PRESSURE IS WEAK AT THE KITCHEN SINK. THIS IS THE CASE WHEN
CUSTOMER IS RUNNING OFF OF FRESH TANK OR HOOKED TO CITY WATER.
The aerator in the faucet was full of plastic.
Took apart and cleaned out the plastic.

71367 4 THE WEIGHT FOR THE FAUCET PULL OUT HOSE FELL OFF. CAN IT BE
ZIPPED TIED BACK INTO PLACE

Claim : 71367

 WO # Job # Description JOB INFORMATION

 .won't stay on hose
 Secured with zip tie.

71367 6 THE INVERTER WE JUST INSTALLED HAS FAILED GIVING A E5 CODE

 Part No Job# Description PARTS Qty Price Total

 12123 5 12123 Inverter - 2000 Watt - 2KW 1.00 553.99 553.99

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 5 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.90 160.00 144.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.90 160.00 144.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.60 160.00 96.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 5 UPS - INVERTER 1.00 24.02 24.02

Parts Total: 553.99
 Labour Total: 640.00
 Sublet Total: 0.00
 Extras Total: 24.02

>>>> Claim Total: 1,218.01

Customer Signature: _____

Date: _____