

Pre-Authorization

9/6/20
04:28:00

Pre-Authorization number PA03518322 Reference no: 71494 Status: Approved Approved by steic Approved date 9/6/2023
Customer Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV
600 E Baseline Rd
Evansville, IN 47725 4YDTSG120R7100209

Item	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5100306B Breakaway Switch	0.00	0.50	0.50		1	0.20	Complaint: CABLE FOR THE BRAKE AWAY HAS CAME LOOSE Cause: Breakaway cable broke Correction: Went to pull breakaway cable and it broke when pulled, the plug never came out. Got with Ben to install new breakaway switch. Cut out bad breakaway switch then spliced in new breakaway switch. Took pictures. Tested.

KRV - The issue submitted is not considered a warranty defect in materials or workmanship.
KRV - Approved as a Goodwill gesture (non-warranty).

Pre-Authorization number PA03518322 0.50

This paper claims ~~only~~ use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the