

Pre-Authorization

Pre-Authorization number PA03597483		Reference no: 72660	Status: Approved	Approved by navra	Approved date 1/11/2024
Servicing Dealer	Name	Address	VIN	Retail sold on	

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSG L21R7100204
------	----------------------	---	--------------------

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2302314B	Compartment Doc	0.00	0.20	0.20		1	0.20	Complaint:DOOR SIDE COMPARTMENT DOOR WONT AUTO LATCH Cause:Auto latch is to far pitched inward Correction:Inspected the auto latch,found that the auto latch was leaning towards the body. With the latch not sitting on a flat spot it would not latch by itself. Would latch manually. Removed the screws and put putty tape behind it to bring it away from the body. Checked the latch again. Now it will latch automatically when the door touches latch. KRV – REPAIR ONLY approved.
2	3300516A	Blind - Vertical - R	0.00	0.10	0.10		1	0.20	Complaint:TOP BUNK BLIND WONT STAY UP Cause:Tension strings were loose Correction:Inspected the blind, found that the tension strings weren't tight enough to hold up the blind. Tightened the tension strings by wrapping up the tension strings.
Pre-Authorization number PA03597483					0.30				

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company