

Pre-Authorization

Pre-Authorization number PA03598054 Reference no: 72661 Status: Approved Approved by hulld Approved date 1/12/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGK23P3103207
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2210206B	Skylight - Interior	0.00	0.30	0.30		1	0.20	Complaint:BATHROOM SKYLIGHT NOT STICKING INSIDE Cause:Skylight piece has came loose. Asking for a new inside assembly for skylight. Correction:Skylight piece has came loose. Asking for a new inside assembly for skylight.
2	2315708A	Window - 48" or l	0.00	0.10	0.10		1	0.50	Complaint:REAR WINDOW RIGHT SIDE TRIM SCRATCHED Cause:Painted over scratch with black paint marker. Correction:Painted over scratch with black paint marker.
3	2315725A	Window - 48" or l	0.00	0.10			1	0.50	Complaint:REAR WINDOW RIGHT SIDE TRIM SCRATCHED Cause:Painted over scratch with black paint marker. Correction:Painted over scratch with black paint marker.
					0.40				KRV - Duplicate line. See line 2.

Pre-Authorization number PA03598054

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company