

Pre-Authorization

Pre-Authorization number PA03675619		Reference no: 73762	Status: Approved	Approved by maist	Approved date 5/30/2024
Servicing Dealer	Name	Address	VIN	Retail sold on	

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGM22R7105152
------	----------------------	---	-------------------

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2302316B	Compartment Doc	0.00	0.20	0.20		1	0.20	Complaint:REAR COMPARTMENT DOOR WONT LATCH Cause:Rear compartment won't latch Correction:Tighten latch on rear compartment door, latches properly
2	2101806B	Roof - Rubber Me	0.00	0.10	2.00		1	1.00	Complaint:HAS NAIL STICKING UP FROM UNDER RUBBER IN REAR. Cause:Nail sticking up under rubber roof at rear.Found a nail sticking up under rubber roof during PDI. Correction:PLEASE ADVISE AS TO WHAT YOU WANT TO DO WITH THIS KRV-Pull the rear molding, lift up membrane, repair nail and lay back down.
					2.20				

Pre-Authorization number PA03675619

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company