

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74324
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 21474 - DAVID W. TURPEN, SR
Address: 1491 REXING RD.
WADESVILLE, IN
47638
Phone: 812-549-1416
Stock Number: 11238 - 2023 MONTANA 3231CK 4YDFM0S22P4700146
VIN: 4YDFM0S22P4700146 HIN: SER#: 4YDFM0S22P4700146
Mileage: 0 Work Order Comp: 23 AUG 24
Auth. No: Dealer #: 1194
Warr. Date: 26 MAR 24 Work Order Date: 25 JUL 24 Inv #: 408535

WO # Job # Description JOB INFORMATION

74324 2 THE MAIN AWNING BLOWS THE FUSE WHEN GOING OUT
awning blowe feuse
removed motor and replacedwith new and the feuse did not break
anymore

74324 1 THE MAIN A/C IN THE REAR OF THE UNIT IS BLOWING HOT
test rear ac unit
amp draw as low on compressor and is not cooling replace ac unit

74324 4 THE STORAGE DOOR ON THE FRONT DOOR SIDE THE CUSTOMER LETS THE
DOOR SLAM SHUT AND NOW IT DOES NOT LOCK HE HAS TO PUSH THE DOOR
CLOSED REAR LATCH
front compartment door not latching in rear
door is in need of adjustment rear slam latch wont latch

74324 6 THE TOP OF THE STEP SQUEEK
top step squeeks and is not tight
step needs shims and screws to tighten step

74324 8 THE PULL HANDLES FOR THE BLACK AND GREY ARE BACKWARDS
black ad grey tank pull valve labels are backwards
removed handles and switch lines and put handles back in proper
place

74324 9 SCREWS ARE MISSING ON THE STEP HANDLE FOR THE ENTRY DOOR
entry door steps handle is missing screw on right side of handle

