

Pre-Authorization

Pre-Authorization number PA03710170		Reference no: 74330		Status: Approved	Approved by stuml	Approved date 7/29/2024
Servicing Dealer	Name	Address		VIN	Retail sold on	
1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725		4YDF25R22LV502731	9/23/2019	

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	7138142A	Safety Advisory 20V398	0.00	0.70	0.70		1	0.70	Complaint: CUSTOMER HAS A RECALL ON THE ANTENNA OF THE COACH. Cause: Removed antenna. Removed base plate. Secured and sealed base plate. Installed 360 antenna to coax. Secured and sealed antenna with dicor Correction: Removed antenna. Removed base plate. Secured and sealed base plate. Installed 360 antenna to coax. Secured and sealed antenna with dicor

Pre-Authorization number PA03710170

0.70For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company