

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 74403
 MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
 Customer: 54547 - BRYAN K. MILLS
 Address: 1502 W CHERRY ST ROBINSON, IL

62454

Phone: 618-554-0410

Stock Number: 10910 - 2024 COUGAR SPORT 2700BH 4YDFCGM26R2500457

VIN: 4YDFCGM26R2500457 HIN: SER#: 4YDFCGM26R2500457

Mileage: 0 Work Order Comp: 09 AUG 24

Auth. No: Dealer #: 1194

Warr. Date: 22 MAR 24 Work Order Date: 02 AUG 24 Inv #: 408054

 WO # Job # Description JOB INFORMATION

74403 2 CUSTOMER ADVISES THAT WHEN HE LOOKS IN HIS REAR VIEW MIRROR, IT
 APPEARS THAT THE CAMPER IS LEANING TO ONE SIDE.
 right rear leaf spring was bent and needed replaced
 i jacked unit up and removed tire from right rear and removed
 hanger bolts and drove them out and removed u bolts and then
 removed spring and replaced with new and drove hanger bolts back
 into place and tightened nut and then put u bolts back into place
 and tightened down then put tire back on and lowered unit back
 down then toqured lugs down to 110 foot pounds

 Part No Job# Description PARTS Qty Price Total

342669 2 Axle - Leaf Spring - 4400# - For 1.00 132.50 132.50

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.50 170.00 85.00
 Z990 2 MISCELLANEOUS REPAIR 0.00 170.00 0.00
 Z990 2 MISCELLANEOUS REPAIR 0.00 170.00 0.00
 Z990 2 MISCELLANEOUS REPAIR 0.00 170.00 0.00

 Excode Job# Description EXTRAS Qty Price Total

FRT 2 UPS-LEAF SPRING 1.00 27.22 27.22

Parts Total: 132.50
 Labour Total: 85.00
 Sublet Total: 0.00

Extras Total: 27.22

>>>> Claim Total: 244.72

Customer Signature: _____

Date: _____

Claim : 74403

```
*****  
Excode   Job#  Description          EXTRAS                Qty    Price    Total  
*****
```