

Pre-Authorization

Pre-Authorization number PA03731020 Reference no: 74559 Status: Approved Approved by stept Approved date 9/4/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDFCGL22RV501525
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5100306B	Breakaway Switch	0.00	0.30			1	0.20	Complaint:BREAK AWAY CABLE COME APART Cause:BRAKE-AWAY SWITCH CABLE CAME APART. Correction:Cable pulled out of plunger. Plunger will not come out of switch. Removed stuck switch. Installed new switch and checked operation. OK KRV – Non-Warranty, Damage: Dealer Pick-Up (DPU) unit. Contact your Transportation Carrier.
2	3300214A	Blind - Venetian -	0.00	0.50	0.20		1	0.20	Complaint:DINING ROOM SLIDE SIDE BLIND IS NOT MOUNTED SECURELY. Cause:DINNING ROOM WINDOW BLIND IS NOT MOUNTED SECURELY Correction:Removed window valance from dinning room window. Remounted roll up blind mounting brackets that were loose. Snapped roll up blind into brackets. Remounted window valance above window. Checked operation of roll up shade. Working ok at this time. KRV- Approved to repair

Pre-Authorization number PA03731020 0.20

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company