

Pre-Authorization

Pre-Authorization number PA03733543		Reference no: 74701	Status: Approved	Approved by stept	Approved date 9/10/2024
Servicing Dealer	Name	Address	VIN	Retail sold on	

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGL22RV501525	8/22/2024
------	----------------------	---	-------------------	-----------

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2103414A	Slide Out - Box - I	0.00	3.00	2.00		1	0.10	Complaint: CUSTOMER ADVISES THAT THE WARDROBE (OFF DOOR FRONT) SLIDE IS BINDING WHEN COMING IN. CUSTOMER ADVISES THAT IT LOOKS LIKE IT IS BINDING ENOUGH THAT SOMETHING MIGHT BREAK. IT IS ALSO BINDING ON THE CARPET WHEN IT COMES IN. NOTE: IN COMMAND CODE IS: 7189 Cause: THE BOTTOM OF THE SLIDE ROOM WAS HITTING THE CARPET OVER THE 5TH WHEEL FRAME Correction: I REMOVED THE LOWER BOARD ON THE SLIDE ROOM AND CUT OFF 1/4 INCH AND REINSTALLED ON THE ROOM FACIA AND THEN I HAD TO CUT 1/4 INCH OFF THE FRONT VERTICAL FACIA AND NOW THE ROOM GOES IN AND OUT WITH OUT GRABBING AT BOTTOM.

Pre-Authorization number PA03733543

2.00

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company