

e-Authorization

9/25/20  
12:27:40 p

|                                   |                     |                  |                   |                         |
|-----------------------------------|---------------------|------------------|-------------------|-------------------------|
| 3-Authorization number PA03741791 | Reference no: 74786 | Status: Approved | Approved by navra | Approved date 9/20/2024 |
| Routing Name                      | Address             | VIN              | Retail sold on    |                         |

|                                   |                             |                                                                   |                   |                   |                 |     |               |                                                                                                                                                                                                                                                     |
|-----------------------------------|-----------------------------|-------------------------------------------------------------------|-------------------|-------------------|-----------------|-----|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 34                                | Basden's American RV        | Basden's American RV<br>600 E Baseline Rd<br>Evansville, IN 47725 | 4YDTSGL21S7100998 |                   |                 |     |               |                                                                                                                                                                                                                                                     |
| du Root<br>e operation<br>of      | Description                 | Sublet                                                            | Sub hours         | Approved<br>hours | Actual<br>hours | Qty | Base<br>hours | Complaint / Cause / Correction                                                                                                                                                                                                                      |
| 1                                 | 3201816A Decorative Wood    | 0.00                                                              | 0.20              | 0.20              |                 | 1   | 0.10          | Complaint:BATHROOM ROOF VENT IS HANGING DOWN<br>Cause:BATHROOM VENT IS HANGING DOWN<br>Correction:Removed ceiling fan trim ring from ceiling. No wood<br>behind two loose screws. Turned trim ring 90 degs and<br>remounted for screws to hit wood. |
| 2                                 | 2300618B Entrance Door - l- | 0.00                                                              | 0.10              | 0.10              |                 | 1   | 0.30          | Complaint:ENTRY DOOR NEEDS ADJUSTED<br>Cause:ENTRY DOOR NEEDS ADJUSTED<br>Correction:Adjusted latch plate on door frame to allow door to<br>close and latch.                                                                                        |
| 3-Authorization number PA03741791 |                             |                                                                   |                   | 0.30              |                 |     |               |                                                                                                                                                                                                                                                     |

r paper claims ~~only~~ use one pre-authorization number per warranty claim for  
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the