

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 75805
 MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
 Customer: 55496 - DAVIE JOHN PAUL CURRY
 Address: 122 COLOMBA RD DEBARY, FL

32713

Phone: 386-337-5454

Stock Number: 11412 - 2024 FREEDOM EXPRESS 298FDS 5ZT2FEVB0RW029702

VIN: 5ZT2FEVB0RW029702 HIN: SER#: 5ZT2FEVB0RW029702

Mileage: 0 Work Order Comp: 31 JAN 25

Auth. No: Dealer #:

Warr. Date: 31 JAN 25 Work Order Date: 14 JAN 25 Inv #: 413888

WO #	Job #	Description	JOB INFORMATION
75805	3	LP WILL NOT HOLD LOOSING PRESSURE Lp leaking after lp drop test I spraied down every line and splitter under unit and around tank hoses then I removed and replaced the lp regulator and did an lp drop test again and found that the leak was no longer present	
75805	2	SOLAR NEGATIVE TERMINAL IS TOO SHORT TO CONNECT TO BATTERY Solar terminal was to short to reach the battery I cut off the ring terminal on the negative side of the solar i then added an 8 inch extension to make the wire long enough to reach	

Part No	Job#	Description	PARTS	Qty	Price	Total
696405	3	RECALL REGULATOR KIT W/HOSES - KE		1.00	28.75	28.75

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00

Parts Total: 28.75
 Labour Total: 119.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 147.75

Customer Signature: _____

Date: _____