

e-Authorization

2/24/20
05:13:59 PM

3- Authorization number PA03806167	Reference no: 75888	Status: Approved	Approved by scott	Approved date 2/6/2025
Customer Name	Address	VIN	Retail sold on	

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTCGN27SV503874	2/20/2025				
In Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2300114A Entrance Door - L	0.00	0.20	0.20		1	0.20	Complaint:REAR DOOR NEEDS ADJUSTED Cause:Rear bunk entry door needs adjusted Correction: The striker plate was hitting the door and not allowing it to close i then hit the strike plate with a hammer and put the strike plate into the correct place then made sure the door closed properly
2	4134208B Refrigerator - Con	0.00	0.25	0.25		1	0.50	Complaint:DENT IN THE OUTSIDE FRIDGE Cause:DENT IN FRIDGE PUT PARTS REQUEST IN FOR NEW FRIDGE Correction:NEED NEW FRIDGE
3	5100614A Breaker, 120V - R	0.00	0.20	0.25		1	0.20	Complaint:OUTLET INTHE CLOSET DOES NOT SIT FLUSH Cause:Outlet cover not able to be mounted properly due the improper mounting of the outlet in the wall Correction:I had to first measure how much needed to be cut off the cover and cut off 1/4 inch of the cover and cleaned un with sand paper and fit into place properly
KRV – Labor time adjusted allowing for proper repair procedure to be performed.								
-Authorization number PA03806167		0.70						

r paper claims only use one pre-authorization number per warranty claim for
to be a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the