

e-Authorization

3-Authorization number PA03817898	Reference no: 75934	Status: Approved	Approved by stept Retail sold on	Approved date 3/4/2025
Tricking Name	Address	VIN		

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTCGM29SV502372	2/22/2025
----	----------------------	---	-------------------	-----------

du Root je operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1216014A Step - Fold Up	0.00	0.20	0.20		1	0.10	Complaint:ENTRY STEPS HIT FIRE EXTINGUISHER WHEN LOWERING Cause:Front entry steps was hitting the fire extinguisher when folding down the steps Correction:Took pictures of the steps hitting the fire extinguisher when folded down. Unscrewed the lag bolts form the step hinge mount and move the steps to the left about a 1/4 inch. Adjusted the step latch as well so the steps fit. Unscrewed the fire extinguisher and moved it 1/4inch to the right away from the steps. Moved the steps down to check for clearance. Now there is a 1/4 inch gap between the steps and the fire extinguisher.

3-Authorization number PA03817898

0.20

For paper claims ~~only~~ use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the