

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76074
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 11527 - 2026 FREELANDER 27QB 1FDWE3FN7SDD32380

VIN: 1FDWE3FN7SDD32380 HIN: SER#: 1FDWE3FN7SDD32380

Mileage: 0

Work Order Comp: 30 JUL 25

Auth. No:

Dealer #:

Warr. Date: 25 APR 25

Work Order Date: 01 MAR 25

Inv #: 420459

WO # Job # Description JOB INFORMATION

76074 3 SHOWER BLEND VLAVE IS LEAKING
 The shower blend valve is leaking internally.

76074 4 THE REAR ROOF TRIM NEEDS DICOR
 There is a gap on the top of the roof trim.
 Received dicor from parts. Got a lift and removed Santander dirt
 from trim and roof. Applied dicor as needed.

76074 5 TANK HEATER FELL OFF GREY TANK

76074 6 SCRTCHES ON STILE ABOVE CABINET DOOR
 The Stile is scratched above cabinets.
 .

76074 7 CABINET DOOR HAS A CHUNK MISSING
 Cabinet door has a chunk missing.

76074 9 DENT ON WALL PANEL IN BEDROOM
 Wall panel in the bedroom has a dent at the top. We will need to
 remove the window, valance, blind and surrounding trim to remove
 and replace the panel.

76074 1 BLACK TANK SENSOR'S WONT READ
 Tank sensors are not reading.
 Tested voltage going into diode pack. The voltage reads 8.5.
 Removed monitor panel on the inside of the coach and tested

Claim : 76074

 WO # Job # Description JOB INFORMATION

 voltage. 14.5 going into to monitor panel. Tested voltage on the
 fresh, grey and black tank wires. All are reading 8.5 volts DC.
 Tested all sensors using a jumper wire and a diode. All sensors
 are working. Replaced scotch lock connectors with wire caps for
 the the positive and negative wires.

76074 2 GREY TANK SENSORS WONT READ
 Tank sensors are not reading.
 Tested voltage going out of monitor panel. Removed scotch lock
 connectors and replaced with wire caps. Filled tank to test
 sensors. Drain tanks.

76074 8 DOORS ABOVE STOVE ARE RUBBING
 Doors are rubbing above the stove.
 Took a hammer and moved the hinges away from each other.

76074 10 BEDROOM COAX HAS AN OPEN CIRCUIT
 There is no signal going to the bedroom cable hook up. I
 installed a coax tester and found an open circuit.
 Removed booster from wall removed power wire. Removed coax that
 was next to bedroom coax. Cut off both cable ends and installed
 new ones. Tester says the cable is good. Installed booster.
 Installed cover plate in bedroom.

76074 12 CURTAIN HANGER NEEDS ADJUSTED
 Curtain hanger is pushing up against the wall.
 Repositioned awafrom the wall. Filled holes with putty.

76074 13 ENTRY DOOR DEAD BOLT WONT LOCK WHEN DOOR IS SHUT
 The deadbolt functions but it won't go into the latch. The
 deadbolt is centered. Need to be advised by warranty for repair.

 Part No Job# Description PARTS Qty Price Total

 F100224120 3 FAUCET - SOP: SHOWER DIVERTER W/ 1.00 13.75 13.75
 13-1287 4 NON SELF LEVELING DICOR 1.00 7.72 7.72
 F100689025 5 HEATER, HOLDING TANK 50 GAL MAX, 1.00 73.20 73.20
 F100403620 6 STILE, FAWN MAPLE 18MM, 2"X8" RAD 8.00 1.00 8.00
 F100583620 7 DOOR, SLB MDF 14 X 32 FAWN MAPLE 1.00 19.38 19.38
 F100583620 7 DOOR, SLB MDF 14 X 32 FAWN MAPLE 1.00 19.38 19.38
 F100583623 9 LAUAN, 1/8" X 48" X 96" VERT GRAD 1.00 57.50 57.50

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00

Claim : 76074

```

*****
Lab Code  Job#  Description                LABOUR                Hrs      Rate      Total
*****
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.40    185.00     74.00
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.20    185.00     37.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.22    185.00     40.70
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.28    185.00     51.80
Z990      6    MISC LABOUR CODE (EXTERNAL)      2.00    185.00    370.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.07    185.00     12.95
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.25    185.00     46.25
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.18    185.00     33.30
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.30    185.00     55.50
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      9    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      9    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      9    MISC LABOUR CODE (EXTERNAL)      1.75    185.00    323.75
Z990      9    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      1   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      1   MISC LABOUR CODE (EXTERNAL)      0.17    185.00     31.45
Z990      1   MISC LABOUR CODE (EXTERNAL)      0.33    185.00     61.05
Z990      2   MISC LABOUR CODE (EXTERNAL)      0.50    185.00     92.50
Z990      8   MISC LABOUR CODE (EXTERNAL)      0.10    185.00     18.50
Z990     10   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990     10   MISC LABOUR CODE (EXTERNAL)      0.70    185.00    129.50
Z990     10   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990     12   MISC LABOUR CODE (EXTERNAL)      0.20    185.00     37.00
Z990     12   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990     12   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990     13   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990     13   MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990     13   MISC LABOUR CODE (EXTERNAL)      0.20    185.00     37.00

```

```

*****
Excode    Job#  Description                EXTRAS                Qty      Price      Total
*****
FRT        3    UPS-FAUCET                      1.00     15.53     15.53
FRT        5    FREIGHT - F.R. PARTS          1.00    130.15    130.15
FRT        7    UPS-CABINET DOORS             1.00     15.51     15.51

```

```

Parts Total:      198.93
Labour Total:    1,452.25
Sublet Total:        0.00
Extras Total:      161.19

```

```

>>>>> Claim Total:      1,812.37

```

Customer Signature: _____

Date: _____

Claim : 76074

```
*****
Excode   Job#   Description      EXTRAS                      Qty    Price    Total
*****
```