

e-Auth

6/2/20
12:31:54

3-Authorization number PA03861018 Reference no: 76809 Status: Approved Approved by parke Approved date 5/30/2025
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSGG13S7103659 5/20/2025
600 E Baseline Rd
Evansville, IN 47725

du Root de operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201816A Decorative Wood	0.00	0.10	0.10		1	0.10	Complaint:SEAM TAPE IS LOOSE RIGHT IN FRONT OF THE BATTERY Cause:Final pdi Correction:Final pdi interior inspection found that the seal tape was coming off front wall by bed. I fixed it the issue.

3-Authorization number PA03861018 0.10

r paper claims only use one pre-authorization number per warranty claim for
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the