



KEYSTONE

Pre-Authorization

Pre-Authorization number: PREAUTH34156 (PA03927732) Reference no. 77947 Status: Approved

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd Evansville, IN 47725 VIN 4YDTSGR29S7100061 Retail sold on 10/3/2025

Root

Operation Description		Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
6201106B	Regulator - Replace	0	0.3	0.3		1	0.3	Complaint: REGULATOR IS NOT ADJUSTING Cause: Replace lp regulator Correction: Too, lines off old lp regulator. And put the line on the new lp regulator. Checked for leaks and found no leaks. New regulator good to go
6100206B	Bath Faucet - Replace	0	0.5	0.5		1	0.5	KRV VCB Complaint: OUTSIDE KITCHEN FAUCET IS LEAKING AT THE HOT KNOB Cause: Faucet leaked at the handle Correction: Replaced faucet and it doesn't leak and it works properly
Pre-Authorization number: PREAUTH34156				0.8				KRV VCB

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.