

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78009
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 55707 - ERIC MIDDENDORF
Address: 1746 E. DELAWARE ST.
EVANSVILLE, IN
47711
Phone: (812) 455-1466
Stock Number: 2022 RAPTOR 362
VIN:
Mileage:
Auth. No:
Warr. Date:

HIN: SER#: 4YDFRPT24NR801021
Work Order Comp: 17 NOV 25
Dealer #: 1194
Work Order Date: 10 OCT 25 Inv #: 424495

WO # Job # Description JOB INFORMATION

78009 1 CUSTOMER ADVISES THAT THE SENSOR ON THE IN COMMAND IS SHOWING THE
LEVEL FOR THE GENERATOR TANK ON THE TOY TANK AND THE LEVEL FOR
THE TOY TANK ON THE GENERATOR TANK. CUSTOMER THINKS THE SENSORS
ARE BACKWARDS
Found the wiring was reversed on the outside monitor.
I corrected the wiring on the outside monitor and made sure it
was reading inside for the genset. The tank is not full. It has
maybe 2 inches of fuel in the bottom.
78009 5 REPLACE THE ROOF VENTS
Turned in request for parts(installed front vent lid on 10/14)
Installed 2 new vent lids
78009 6 REPLACE THE ROOF UNDER WARRANTY CUSTOMER THINKS THERE IS A SOFT
SPOT IN FRONT OF THE SOLAR PANEL. PLEASE CHECK
The roof is soft. I fou d where the roof looks torn in between
the sewer vent and the solar connector
Sealed spot on roof. Around sewer vent and the solar connector.
The roof is very soft and dangerous in front of the solar
panels.

Part No Job# Description PARTS Qty Price Total

MXA10A40002K 5 VENT LID ASSEMBLY FOR 4000K WHITE 1.00 56.52 56.52
CMC40182 5 40182 PW VENT LID VENTLINE '08 UP 1.00 18.27 18.27

Claim : 78009

Part No	Job#	Description	PARTS	Qty	Price	Total
JRP02-29125	6	ATTIC VENT/PW - KEYSTONE		2.00	11.62	23.24
CMC40033	6	40033 REPLACE ALL PLUMBING VENT		2.00	8.09	16.18
376374	6	Adhesive - Roof - 8010 - 1 Gal/Ca		2.00	72.70	145.40
639157	6	Sealant - Lap Caulk - 5160 White		4.00	20.40	81.60
639155	6	Sealant - Self Leveling - 5121 Al		10.00	12.62	126.20
679920	6	Roof - Membrane - 9.5' x 45' - Al		1.00	572.35	572.35
DCR551LSB-1	6	551LSB-1 BLACK NON SAG DICOR		1.00	8.72	8.72
SIK432053	6	CLEAR SIKASIL PLUS		1.00	10.87	10.87
520357	6	1/4" UNDERLAYMENT		10.00	42.87	428.70
220849	6	CONSTRUCTION ADHESIVE		12.00	4.65	55.80
53165	6	DECKING SEAM TAPE		2.00	19.47	38.94
12246	6	WOOD DECKING		1.00	26.23	26.23

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.03	180.00	5.40
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.46	180.00	262.80
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.09	180.00	196.20
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	180.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.37	180.00	66.60
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.23	180.00	41.40
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	180.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	180.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	180.00	0.00
Z990	6	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	6	MISCELLANEOUS REPAIR		1.48	180.00	266.40
Z990	6	MISCELLANEOUS REPAIR		5.85	180.00	1053.00
Z990	6	MISCELLANEOUS REPAIR		0.30	180.00	54.00
Z990	6	MISCELLANEOUS REPAIR		3.67	180.00	660.60
Z990	6	MISCELLANEOUS REPAIR		4.16	180.00	748.80
Z990	6	MISCELLANEOUS REPAIR		1.29	180.00	232.20
Z990	6	MISCELLANEOUS REPAIR		4.26	180.00	766.80
Z990	6	MISCELLANEOUS REPAIR		3.78	180.00	680.40
Z990	6	MISCELLANEOUS REPAIR		4.11	180.00	739.80
Z990	6	MISCELLANEOUS REPAIR		2.67	180.00	480.60
Z990	6	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	6	MISCELLANEOUS REPAIR		4.17	180.00	750.60
Z990	6	MISCELLANEOUS REPAIR		3.96	180.00	712.80
Z990	6	MISCELLANEOUS REPAIR		2.30	180.00	414.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
SS	1	SHOP SUPPLIES		1.00	41.81	41.81
FRT	6	UPS-SEALER		1.00	14.08	14.08
FRT	6	FREIGHT		1.00	153.93	153.93

Parts Total: 1,609.02
 Labour Total: 8,132.40
 Sublet Total: 0.00
 Extras Total: 209.82

>>>> Claim Total: 9,951.24

Customer Signature: _____

Date: _____

Claim : 78009

```
*****
Excode   Job#   Description      EXTRAS              Qty    Price    Total
*****
```